

Service Bulletin
Product Update
SmartFlo™ Pull Handles
201602003



As part of their commitment to continuous improvement, Crystal Mountain has made a change to the mold for the SmartFlo™ manifold. It has come to our attention that some individuals were having trouble removing the SmartFlo™ from the unit. To that end we added two areas that can serve as a pull handle on either side of the manifold body. The picture on the left shows the SmartFlo™ before the change, while the image on the right shows a SmartFlo™ with the two “handles.” This change was effective starting with serial number 19160910123. Once current replacement stock is depleted, new parts will have the pull handles. If you have any questions about this change, please contact the Crystal Mountain Service department.

BEFORE



AFTER

